

# Carrier Tape Process Flow Diagrams

Number	Steps	Flow Chart				Version: A2	Document no: SH-QWI-08	
							Date: 2020.07.22	
		Stock △	Inspect ◇	Manufacture □	Move ○	Details		
1	Picking materials				○ 1	a. According to production order to pick up the required materials		
2	Tooling assemble			□ 2		a. According to actual production to adjust tooling		
3	Mold temperature/heating			□ 3		a. Power open or not b. Temperature setting inspection, perform 《manufacturing specification》		
4	Forming			□ 4		a. Tooling measurement inspection b. Tooling stripped confirm c. Carrier tape pocket dimension confirm		
5	Punching			□ 5		a. Tape punching position confirm b. Burr inspection after punching		
6	Winding			□ 6		a. Normal inspection		
7	QC Inspection		◇ 7			a. Normal inspection		
8	Package			□ 8		a. Normal inspection		
9	Storage	△ 9				Stockage		
Revision	Version	Y M D						
	A1	2020/11/6						
	A2	2020/12/8						